

63-67 Nova Hard Top Rear  
Left Side

On 63, 64, & 65 models, the bracket in the center of the window guild channel must be removed for motor clearance.

On 66 and 67 models, there is not a center bracket on the guild channel.

