


73-79 Ford Truck
Left Side



*Stop is on regulator.

*If using after-market speakers, they could interfere with the gear on regulator. If this happens, speaker will need to be shimmed out.