

The manual idler bars on the 70-74 Challenger has a different location from the power window idler bars.

Replace the manual idler bar with the idler bar included in the kit.

Note the marked direction for installation.