


63-91 Avanti  
Right Side

\*This shows how regulator hangs inside the door. It is not shipped in this position.

\*An additional bracket can be made and attached to motor and door for extra support when shutting the door.



On the inside of some doors, there is a rib that needs to be ground down for motor clearance.