


60-63 Chevy Truck  
Left Side



Factory window stop is not used. Regulator has stop built into it.

Idler Bar Welded In Place

4 Mounting Holes